BUYER BROCHURE

5652 Colfax Ave S



Photos & Video Tour at 5652COLFAX.COM

HOME HIGHLIGHTS

5652 Colfax Ave S

Photos & Video Tour at 5652COLFAX.COM

HOME HIGHLIGHTS

UPDATES

- New Garage Overhead Door (2022)
- New Kitchen Remodel (2021) Featuring:
 - · Michaelangelo Quartz Counters
 - Custom White Oak Cabinetry
 - Luxury Brass Fixtures. & Kohler Sink
 - GE Cafe French Door Refrigerator
 - · Hallman Professional Gas Italian Range
- New Master Suite Addition/Remodel (2020) Featuring:
 - Spacious Vaulted Master Suite
 - · White Quartz Bath Counters & White Oak Vanity
 - Separate Soaking Tub & Shower with Rejuvenation Fixtures
 - Gorgeous Sitting Area
 - · Huge Walk-in Closet & Laundry with White Oak Beam Ceiling
- New Mud/Sun Room (2020)
- New Marvin Elevate Windows (2020)
- New Roof & HVAC (2020)
- New Backyard Path (2019)
- LL Bath Remodel, Walls & Fireplace Painted (2018)
- New Wood Privacy Fence (2017)


FEATURES

- Charming Two Story near Kenny School & Park
- Luxury Addition/Remodel in 2020-21
- Generous Corner Lot with Flagstone Patio
- 35' Master Suite with Bath, Sitting Area, Walk-in Closet, & Laundry
- Kitchen Remodel with High-End Cabinetry & Appliances
- Spectacular Combo Mud Room-Sun Room!
- Finished Lower Level with FR, Guest BR/BA, Office & 2nd Laundry

FLOOR PLANS


5652 Colfax Ave S

Photos & Video Tour at 5652COLFAX.COM




С

*Disclaimer: This is an opinion of the square footage of this property. All information is deemed reliable, but is not guaranteed and should be independently verified.



		_
First Floor	(Foundation 1247 Sq ft)	1247 Sq ft
Second Flo	or	940 Sq ft
Total Abov	e Grade Finished Sq Ft	2187 Sq ft
Total Build	ing Finished Sq Ft	3155 Sq ft
Basement		1043 Sq ft
Basement	Finished Sq Ft	968 Sq ft
Total Build	ing Sq Ft	3230 Sq ft
Patio		334 Sq ft
Garage	20*12	252 Sq ft



SELLER DISCLOSURES

5652 Colfax Ave S

Photos & Video Tour at 5652COLFAX.COM

Sotheby's Lakes

Has the title been surrendered to the Registrar of Motor Vehicles for cancellation?

5.

6.

7.

8.

9. 10.

11.

12.

13.

14.

15.

16.

17.

18.

19.

20.

21.

22.

23.

24.

25.

26.

27.

28.

29.

30.

31.

32.

33.

34.

35.

36. 37.

38.

39.

40.

41.

42. 43.

44.

45.

46.

47.

TRANSACTIONS

If "Yes," HUD #(s) is/are

DISCLOSURE STATEMENT: SELLER'S PROPERTY DISCLOSURE STATEMENT

This form approved by the Minnesota Association of REALTORS®, which disclaims any liability arising out of use or misuse of this form. © 2022 Minnesota Association of REALTORS®, Minnetonka, MN

	1	. Date	August	09	2022
	2 3 4	. REPO	1 of 10 RTS, IF ANY, ARE OF THIS DISCLOS		
	THE INFORMATION DISCLOSED IS GIVEN TO	THE BE	ST OF SELLER'S	S KNOWLEDGE.	
Under I disclos an ordi MN Sta closing of any f Buyer's Seller h form for kind by	E: This Disclosure Statement satisfies the disclosure Minnesota law, sellers of residential property, with lime to prospective buyers all material facts of which Senary buyer's use or enjoyment of the property or any atute 513.58 requires Seller to notify buyer in writing a fit if Seller learns that Seller's disclosure was inaccurated acts disclosed here (new or changed) of which Seller use or enjoyment of the property or any intended used disclosure alternatives allowed by MN Statutes. So further information regarding disclosure alternatives. It is seller or licensee(s) representing or assisting an expections or warranties the party(ies) may wish to	lited exceller is away intended as soon a s. Seller is is aware to see Disclose This disc by party in	eptions listed on pare that could adverse of the property obligated to continuate could adverse property that occurs sure Statement: Selosure is not a wa	age nine (9), are of ersely and significe erty of which Selle sible, but in any ere nue to notify Buye ely and significant our up to the time eller's Disclosure Autranty or a guaranters	obligated to eantly affect er is aware. vent before r, in writing, y affect the of closing. Alternatives intee of any
For pur	poses of the seller disclosure requirements of MN St	atutes 51	3.52 through 513.	60:	
single-f	ential real property" or "residential real estate" means family residence, including a unit in a common inter (10), regardless of whether the unit is in a common in	est comr	munity as defined	in MN Statute 5	15B.1-103,
	ler disclosure requirements of MN Statutes 513.52 tial real estate, whether by sale, exchange, deed, cor ption.				
inspect the que	JCTIONS TO BUYER: Buyers are encouraged to ed by a third party, and to inquire about any specific a stions listed below, it does not necessarily mean that sly. "NO" may mean that Seller is unaware.	reas of co	oncern. NOTE: If S	Seller answers "NO	D" to any of
inspect knowled (6) If an	JCTIONS TO SELLER: (1) Complete this form you ion report(s) when completing this form. (3) Describ dge. (4) Attach additional pages, with your signature, y items do not apply, write "NA" (not applicable).	e condition	ons affecting the	property to the b	est of your
and the same of th	y located at 5652 Colfax Ave S		80		
- CO. C. B. CO. C. C.		inty of He	nnepin		- 1
State of	Minnesota, Zip Code 55419		("Property")		
	ERAL INFORMATION: The following questions are t			of Seller's knowle	dge.
(1)	What date did you X Acquire Build the home?	2014	1		
(2)	Type of title evidence: Abstract X Registered Location of Abstract:	Torrens)	Unknown		
	Is there an existing Owner's Title Insurance Policy?			Yes	No
(3)	Have you occupied this home continuously during y		(B) (C) (C)	Yes	X No
	If "No," explain: Rested for two years	while	ex-husband	in business	school
	Is the home suitable for year-round use?			Yes Yes	☐ No
	Are you in possession of prior seller's disclosure state. Does the Property include a manufactured home?	tement(s)	? (If "Yes," please	attach.) Yes	X No

✓ Minnesota

XNo

Yes

49.			THE INFORMATION DISC	CLOSED IS GIVEN TO T	HE BEST OF	SELLER'S KI	NOWLEDGE.	
50.	Prope	erty Io	ocated at 5652 Colf	ax Ave S	Mir	neapolis	MN 5	5419
51.	(7	7) Is	the Property located on a	public or a private road?	N Public	Private	Public: no ma	aintenance
52.	3)		ood Insurance: All propertie		ta have been a	ssigned a floo	od zone designat	tion. Some
53.			od zones may require floo					NZI
54.		(a)	Do you know which zone	e the Property is located	in?		Yes	X No
55.			If "Yes," which zone?					F70
56.		(b)	Have you ever had a floo	65 10			Yes	X No
57.			If "Yes," is the policy in f				Yes	☐ No
58.			If "Yes," what is the annu					
59.			If "Yes," who is the insura				377 399	Jan 18
60.		(c)	Have you ever had a cla	im with a flood insurance	carrier or FEN	/A?	Yes	X No
61.			If "Yes," please explain: _					
62.								
64. 65. 66. 67.	u 17		previously charged to premiums paid for flow will apply after Buye	asing, and in some cases for flood insurance for the ood insurance on this Pro r completes their purcha	ne Property. As	s a result, Buy	yer should not r	ely on the
68. 69.	Are th			or aboved assocition				ΓSA.
70.	(9	100 mg	nomeowners associations encroachments?	or snared amenities?			Yes Yes	X No
71.		101.00	ovenants, historical regist	try, reservations, or restri	ctions, that aff	ect	103	N INC
72.		C	or may affect the use or fur	ture resale of the Propert	y?		Yes	≥ No
73.	(1		overnmental requirement				-	926
74.			njoyment of the Property	iger gast berifter som veg staten av samtil		rming use, etc		X No
75.			asements, other than utili				Yes	X No
76.	(1	4) F	Please provide clarification	or further explanation for	or all applicable	e "Yes" respor	nses in Section A	٨:
77.		0						
78.		-						
79. 80.			RAL CONDITION: To your ly exist on the Property?					or do they
81.			(ANSWERS APPLY TO	D ALL STRUCTURES, SU	JCH AS GARA	GE AND OUT	BUILDINGS.)	
82.	(1) Ha	s there been any damage	by wind, fire, flood, hail,	or other cause	(s)?	Yes	X No
83.		If "	Yes," give details of what h	appened and when:		10000	20003	30000
84.			(0. 35)					
85.	(2)) Ha	ve you ever had an insura	nce claim(s) related to th	e Property?		Yes	⊠ No
86.			Yes," what was the claim(s				Victoria	V2, 1.0
B7.		11000	oo, maa was tile olailii(s	, .or (o.g., nan damage to		77		
01.		Did	you receive compensatio	on for the eleim(e)(
QΩ				(A) (A)			Yes Yes	∐ No □ No
		Did					Voe	INO
88. 89. 90.			you have the items repair at dates did the claim(s) o					

92.		THE INFORMATION DISCLOSED IS GIVEN TO THE BEST OF SELLER'S KNOWLEDGE.	
93.	Proper	rty located at 5652 Colfax Ave S Minneapolis MN 5541	9
94. 95. 96.	(3)	 (a) Has/Have the structure(s) been altered? (e.g., additions, altered roof lines, changes to load-bearing walls) If "Yes," please specify what was done, when, and by whom (owner or contractor): 	No
97.		Upstains addition, new roof / altered not line,	
98.		Kitchen remodel, lover fireplace/Hoors/lights	
99. 100.		(b) Has any work been performed on the Property? (e.g., additions to the Property, wiring, plumbing, retaining wall, general finishing) ✓ Yes	□ No
101.		If "Yes," please explain: addition + Kitchen remodel, wining,	
102.		plumbing for upstairs, general finishing	
103. 104.		(c) Are you aware of any work performed on the Property for which appropriate permits were not obtained?	⋈ No
105.		If "Yes," please explain:	
106.			
107.	(4)	Has there been any damage to flooring or floor covering?	⊠ No
108.		If "Yes," give details of what happened and when:	
109.			
110.	(5)	Do you have or have you previously had any pets?	No
111.		If "Yes," indicate type Golden retriever and number	
112.	(6)	THE FOUNDATION: The type of foundation is (i.e., block, poured, wood, stone, other):	
113.	0.000	Unknown	
114.	(7)	THE BASEMENT, CRAWLSPACE, SLAB:	
115.		(a) cracked floor/walls? ☐ Yes ☒ No (e) leakage/seepage? ☐ Yes	X No
116.		(b) drain tile problem? ☐ Yes ☐ No (f) sewer backup? ☐ Yes	No.
117.		(c) flooding? Yes No (g) wet floors/walls? Yes	☐ No
118.		(d) foundation problem? Yes No (h) other? Yes	X No
119.		Give details to any questions answered "Yes":	
120.		Wet flows (minimal) due to running toilet	
121.		7	
122.	(8)	THE ROOF:	
123.		(a) What is the age of the roofing material?	
124.		Home: 2 years Garage(s)/Outbuilding(s): unknown years	
125.		(b) Has there been any interior or exterior damage? ☐ Yes 🔀 No	į.
126.		(c) Has there been interior damage from ice buildup? ☐ Yes ☐ No	Ċ
127.		(d) Has there been any leakage?	
128.		(e) Have there been any repairs or replacements made to the roof? ☐ Yes ☐ No	
129.		Give details to any questions answered "Yes": Roof of home redone in 2010)
130.			



132.	THE INFORMATIO	N DISCLOSE	DISG	IVEN	TO THE BEST OF SELLER'S K	NOWLEDGE.		
133.	Property located at 5652	Colfax Ave	s		Minneapolis	МИ	55419	
134.	(9) THE EXTERIOR AND	INTERIOR W	/ALLS	/SIDIN	G/WINDOWS:			
135.	(a) The type(s) of siding				(1 2-1(1)	d		
136.	(b) cracks/damage?	g 10 (0.g., vii iy i	otaco	, 01101	, 00101).	Telans 85	X No	
137.	(c) leakage/seepage?						No	
138.	5000 3000 SEC						Andrews .	
	(d) other?			2022		Yes	X No	
139.	Give details to any que	estions answe	red "Ye	s":				
140.		5752 075 070 0752 UV 0752 T						
141.					L, AND OTHER MECHANICAL			
142.					cated on the Property. Check "			
143.			s not ir	work	ing condition. Working order me	ans all compoi	nents o	of the
144. 145.	items specified be	elow.	Mor	lein m			Mar	alaim n
146.			Wor				Ord	rking
147.		NA	Yes	No		NA		
148.	Air-conditioning	-	X	П	Pool and equipment		- Innerental	
149.	Central Wall		Lacas		Propane tank			П
150.	Air exchange system		X		Rented Owned	CALL CONTRACTOR OF THE PARTY OF		
151.	Carbon monoxide detector		X		Range/oven		X	
152.	Ceiling fan				Range hood		X	П
153.	Central vacuum		Ħ	П	Refrigerator		X	П
154.	Clothes dryer	Land .	×		Security system			П
155.	Clothes washer	Service and a service of the service	XXXX		Rented Owned			
156.	Dishwasher		X	П	Smoke detectors (battery)		V	
157.	Doorbell		X	Ħ	Smoke detectors (hardwired)			П
158.	Drain tile system	- Company of the Comp		П	Solar collectors	5 7	П	П
159.	Electrical system		X	Ħ	Sump pump	Tanaba .		Ħ
160.	Environmental remediation		Q.S.		Toilet mechanisms		X	Ħ
161.	(e.g., radon, vapor intrusio	[a.]		П	Trash compactor			П
162.	Exhaust system		П		TV antenna system	[K 7]		Ħ
163.	Fire sprinkler system		П	Ħ	TV cable system		X	Ħ
164.	Fireplace		V	Ħ	TV receiver			Н
165.	Fireplace mechanisms		X	П	TV satellite dish	- Indiana	X	\Box
166.	Freezer		V	Ħ	Rented Owned		12.0	
167.	Furnace humidifier		X	П	Water heater		X	
168.	Garage door auto reverse			П	Water purification system			H
169.	Garage door opener			П	Rented Owned		ш	ш
170.	Garage door opener remo			Ħ	Water softener		X	
171.	1701		V	\equiv	Rented Owned		12.5	
171.	Garbage disposal		X	H		$\mathbf{\nabla}$		
173.	Heating system (central)	E 20	20		Water treatment system			
174.	Heating system (suppleme	S 2	H	H	Windows		V	
174.	Incinerator Intercom			H	Windows treatments		X	H
175.				H		Fr. 42		H
176.	In-ground pet containment	95	X	H	Wood-burning stove		H	
177.	Lawn sprinkler system		X	H	Other		H	H
	Microwave		V	H	Other		\vdash	
179.	Plumbing				Other			



181.		THE INFORMAT	ION DISCLOSED IS GIVE	N TO THE BES	T OF SELLER'S KN	OWLEDGE.	
182.	Pro	operty located at 5652	Colfax Ave S		Minneapolis	MN	55419
183.			ystems on the Property co	onnected or con	trolled wirelessly		
184.			"), to a router or gateway			X Yes	No
185.		Comments regarding iss	sues in Section C: Ser			ritor,	
186.				verizon	internet		
187. 188. 189.	D.	(A subsurface sewage tr	GE TREATMENT SYSTEM reatment system disclosur S NOT know of a subsurface	e is required by	MN Statute 115.55.)		
190.		- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	is DOES, and the system	n does not requ	uire a state permit, se	ee Disclosure	Statement:
191.		Subsurface Sewage Trea	10 CO 5000 EV		N 2 2 30	1 01 72	
192. 193.			ned subsurface sewage tre tement: Subsurface Sewag			oed real Prop	perty.
194. 195.	E.	PRIVATE WELL DISCL	OSURE: (A well disclosure	e and Certificate	are required by MN	Statute 103I.	.235.)
196.			w of any wells on the abov	e-described rea	al Property.		
197.			re wells located on the ab		51 15	closure State	ement: Well.)
198.		☐ This Property is in a	Special Well Construction	Area.	Parter by at 1000 At 100 and Tube of the form the control of the		
199.		There are wells serv	ing the above-described F	Property that are	not located on the P	roperty.	
200.			erties or residences does		serve?		
201.			enance agreement for the			Yes	☐ No
202.		If "Yes," what is	the annual maintenance fe	e? \$			
203. 204. 205. 206. 207.	F.		ax Treatment o any preferential property e.g., Disabled Veterans' B			Yes	⊠ No
208.		If "Yes," would these ter	minate upon the sale of th	e Property?		Yes	☐ No
209.		Explain:					
210.		2					
211. 212. 213.	G.	provides that a transfere	FIN REAL PROPERTY TA e ("Buyer") of a United Sta eror ("Seller") is a foreign p	ates real propert	y interest must be no	tified in writi	ng and must
214.		Seller represents that Sell	er IS IS NOT a foreign	n person (i.e., a n	on-resident alien indiv	idual, foreign	corporation,
215. 216.			ign trust, or foreign estate y transaction involving the			This represe	ntation shall
217. 218. 219. 220. 221. 222.		transaction (unle exempt transact If the above ans	swer is "IS," Buyer may bess the transaction is cover ions, Buyer may be liable wer is "IS NOT," Buyer may t from the withholding rec	red by an applica for the tax if Bu ay wish to obtain	able exception to FIR yer fails to withhold. n specific documenta	PTA withhold	ling). In non- ller ensuring
223. 224. 225. 226.	ope	for withholding the appli FIRPTA compliance, as	and potential risks of fail cable tax, Buyer and Selle the respective licensee other the transaction is e	er should seek a es representing	appropriate legal an or assisting either	d tax advice party will b	e regarding e unable to

228.		THE INFORMATION DISCLOSED IS	SIVEN TO T	HE BEST OF SELLER'S KNOW	LEDGE.	01
229.	Pro	operty located at 5652 Colfax Ave S		Minneapolis	MN	55419
230. 231. 232. 233. 234.	H.	METHAMPHETAMINE PRODUCTION DISCL (A Methamphetamine Production Disclosure is Seller is not aware of any methamphetamine pro (See Disclosure Statement: Methamphetam	s required by ine production oduction has	on that has occurred on the Prop occurred on the Property.		
235. 236. 237. 238. 239.	I.	NOTICE REGARDING AIRPORT ZONING R zone with zoning regulations adopted by the go are filed with the county recorder in each coun if such zoning regulations affect the Property, located.	overning bod nty where the	y that may affect the Property. Suc e zoned area is located. If you wo	ch zonin uld like	g regulations to determine
240. 241. 242.	J.	NOTICE REGARDING CARBON MONOXIDE Detectors to be located within ten (10) feet from be personal property and may or may not be it	m all sleeping	g rooms. Carbon Monoxide Detec		
243.	K.	CEMETERY ACT: The following questions are	to be answ	ered to the best of Seller's knowl	edge.	
244. 245. 246.		MN Statute 307.08 prohibits any damage or person who intentionally, willfully and knowingl remains or human burial grounds is guilty of a	ly destroys, r			
247.		Are you aware of any human remains, burials,	or cemeterie	es located on the Property?	Yes	⋈ No
248.		If "Yes," please explain:				
249. 250. 251.		All unidentified human remains or burials for contexts which indicate antiquity greater than Statute 307.08, Subd. 7.				
252.	L.	ENVIRONMENTAL CONCERNS: To your kno	owledge, hav	ve any of the following previously	y existe	d or do they
253. 254. 255. 256. 257. 258.		currently exist on the Property? (1) Animal/Insect/Pest Infestation? Yes (2) Asbestos? Yes (3) Diseased trees? Yes (4) Formaldehyde? Yes (5) Hazardous waste/substances? Yes	No No No No No	(6) Lead? (e.g., paint, plumbing)(7) Mold?(8) Soil problems?(9) Underground storage tanks?(10) Vapor intrusion?	Yes Yes Yes Yes Yes	X No X No X No X No X No
259.		(11) Other?	23110	(10) vapor intradion:	Yes	□No
260. 261. 262.		Have you ever been contacted or received authority pertaining to possible or actual eintrusion, drinking water, and/or soil contacted.	environment	al contamination (e.g., vapor	Yes	∑ No
263. 264.		(13) Are you aware if there are currently, or have on the Property by any governmental authors.	ve previously	been, any orders issued		
265. 266.		public health nuisance on the Property? If answer above is "Yes," all orders HA	VE HAV	E NOT been vacated.	Yes	⊠ No
267. 268. 269.		(14) Please provide clarification or further expl	anation for a	all applicable "Yes" responses in	Section	L.
270.						-
271.						



273.			THE INFORMATI	ON DISCLOSED IS GIVEN	TO THE BEST OF SELLER'S KNOW	VLEDGE	
274.	Pro	perty lo	cated at 5652	Colfax Ave S	Minneapolis	MN	55419
275.	M.	RADO	N DISCLOSURE:	(The following Seller disclo	sure satisfies MN Statute 144.496.)		
276. 277. 278. 279.		homeb having	ouyers have an in the radon levels r	door radon test performed nitigated if elevated radon o	a Department of Health strongly re prior to purchase or taking occupan oncentrations are found. Elevated radd d, if applicable, radon mitigator.	cy, and	recommends
280. 281. 282. 283. 284.		danger Radon cause	rous levels of indo , a Class A human overall. The selle	or radon gas that may place carcinogen, is the leading o	erty is notified that the property may occupants at risk of developing rador cause of lung cancer in nonsmokers at tial real property is required to provid	induced nd the se	d lung cancer. econd leading
285. 286. 287.		Depart	ment of Health's	publication entitled Radon i	ent, Buyer hereby acknowledges rec in Real Estate Transactions, which is es/environment/air/radon/radonre.htm	s attache	
288. 289. 290. 291. 292.		pertain Statute the cou	ing to radon conce 144.496 may brir	entrations in the Property, is l ng a civil action and recover on nust be commenced wit	d under MN Statute 144.496, and is a liable to the Buyer. A buyer who is injure damages and receive other equitable r thin two years after the date on which	ed by a vi	olation of MN etermined by
293. 294. 295.		knowle	edge. Radon test(s)	HAVE HAVE NOT occu	representations made by Seller to the e rred on the Property.	xtent of S	Seller's actual
296. 297. 298.		(b)			nitigation, or remediation. NOTE: Selle lon concentration within the dwelling:	r shall att	ach the most
299. 300.		(c)	There ISXI	S NOT a radon mitigation s	ystem currently installed on the Prope	erty.	
301. 302. 303.				ll disclose, if known, informa	tion regarding the radon mitigation sys	tem, inclu	uding system
304.					90. 72		
305.		EXCEP	PTIONS: See Sect	ion R for exceptions to this	disclosure requirement.		
306. 307.	N.		ES/OTHER DEFE knowledge.	CTS/MATERIAL FACTS: 1	The following questions are to be ans	wered to	the best of
308.		Notice	s: Seller 🗌 HAS	HAS NOT received a not	ice regarding any proposed improven	nent proj	ect from any
309.		assessi			be assessed against the Property. If	"HAS," p	olease attach
310.		and/or	explain:				
311.							
312.							
313.		-					



315.	THE INFORMAT	THE INFORMATION DISCLOSED IS GIVEN TO THE BEST OF SELLER'S KNOWLEDGE.						
316.	Property located at 5652	Colfax Ave S	Minneapolis	MN	55419			
317. 318.		집에 집에 가는 그리고 있는 것이 없는 것이 없는 가는 것이 없는 것이 없다.	erial facts that could adversely an ny intended use of the Property?	d significa	intly affect an			
319.	If "Yes," explain:							
320.	102							
321.								
322.								
323.								
324. 325. 326.			have shown that various forms or moisture entering the home a					
327.	Examples of exterior mo							
328. 329.	improper flashingimproper grading,	around windows and doors,						
330.	 flooding, 							
331.	roof leaks.	92						
332. 333.	Examples of interior mo • plumbing leaks,	isture sources may be:						
334.	 condensation (car 		too high or surfaces that are too o	old),				
335. 336.	 overflow from tub firewood stored in 							
337. 338.	 humidifier use, inadequate vention 	g of kitchen and bath humidity,						
339.	 improper venting 	of clothes dryer exhaust outdoo						
340. 341.	 line-drying laundry houseplants—wat 	y indoors, tering them can generate large	amounts of moisture					
342.			ion may do to the Property, water in	ntrusion m	ay also result			
343. 344.		nildew, and other fungi. Mold grortant to detect and remediate	owth may also cause structural d	amage to	the Property.			
345. 346. 347. 348.	humans. However, mold	ds have the ability to produce	th indoors and outdoors. Many r mycotoxins that may have a pote ised individuals and people who h	ential to c	ause serious			
349. 350. 351. 352. 353.	have a concern about war Property inspected for r	terintrusion or the resulting mold noisture problems before enter	etect, as it frequently grows within the street, as it frequently grows within the street was wardened as the street with the street as the street with the street as the street with the stre	ntto consid as a cond	derhaving the dition of your			
354. 355. 356. 357. 358.	offender registry and p may be obtained by co is located or the Minr	persons registered with the pontacting the local law enforce	FORMATION: Information regardatory offender registry under ement offices in the communitations at (651) 361-7200, or from	er MN Sta y where t	tue 243.166 he property			



359. Page 9

360.		TH	E INFORMAT	ION DISCLOSED IS GIVEN TO	THE BEST OF SELLER'S KNO	WLEDGE	
361.	Prope	rty locat	ed at 5652	Colfax Ave S	Minneapolis	MN	55419
				THROUGH 513.60: SELLER'S	MATERIAL FACT DISCLOSURE	:	
363.	E	ception	ns: The seller	disclosure requirements of MN	Statutes 513.52 through 513.60 D	O NOT a	pply to
364.		(1)		that is not residential real prope			
365.		(2)	a gratuitous ti	ransfer;	1999		
366.		(3)	a transfer pur	suant to a court order;			
367.		(4)	a transfer to a	government or governmental a	igency;		
368.				foreclosure or deed in lieu of for			
369.				eirs or devisees of a decedent;			
370.		2000		n a co-tenant to one or more ot	10. M(C) (Mark 10) 1 M(C) (Mark 10) (M(C) (M)		
371.					erent, child, or grandchild of Seller		
372.		(9)			a decree of marriage dissolution	on or from	n a property
373.				cidental to that decree;			
374.					operty that has not been inhabited	1;	
375.					erest community, until exercised;		
376.		0.00		: [1] [1] [1] [1] [1] [1] [1] [1] [1] [1]	ntrolled by the grantor as those t	erms are	defined with
377.				eclarant under section 515B.1-			
378.					the residential real property; or		
379.		(14)	a transfer of s	pecial declarant rights under se	ection 515B.3-104.		
380.	MI	N STAT	JTES 144.496	S: RADON AWARENESS ACT			
381.	Th	e seller	disclosure red	quirements of MN Statute 144.4	196 DO NOT apply to (1)-(9) and (11)-(14) a	bove. Sellers
382.	of	newly c	onstructed res	sidential property must comply	with the disclosure requirements o	of MN Star	tute 144.496.
383.	Wa	aiver: T	he written dis	sclosure required under sectio	ns 513.52 to 513.60 may be wa	aived if S	eller and the
384.					sure required under sections 513.		
385.	wa	aive, lim	t, or abridge a	any obligation for seller disclosu	re created by any other law.		
386.	No	Duty t	o Disclose:				
387.	(A)	There	is no duty to d	disclose the fact that the Proper	ty		
388.	9769	(1) is	or was occup	pied by an owner or occupant	who is or was suspected to be	infected	with Human
389.		Im	munodeficien	cy Virus or diagnosed with Acq	uired Immunodeficiency Syndrom	e;	
390.		(2) wa	as the site of a	a suicide, accidental death, natu	iral death, or perceived paranorma	al activity	or
391.		(3) is	located in a n	eighborhood containing any ad	ult family home, community-base	d residen	tial facility, or
392.		nu	irsing home.				
393.	(B)	Preda	tory Offende	rs. There is no duty to disclos	e information regarding an offend	der who i	s required to
394.	1-7			HONG CORNERS STOP - 400 HONG CORNERS (CORNERS CORNERS CORNERS CORNERS CORNERS CORNERS CORNERS CORNERS CORNERS C	otification is made under that sect		
395.					on about the predatory offender		
396.					ontacting the local law enforcem		
397.				or the Department of Correction		3	•
398.	(C)	The n	ovisions in na	ragraphs (A) and (B) do not cres	ate a duty to disclose any facts de	scribed in	naragraphs
399.	(0)			rty that is not residential proper		.oonbod ii	r paragrapho
400.	(D)	Inspe	ctions.	100 ST 100	573		
401.	(3)			ded in paragraph (2). Seller is	not required to disclose informati	on relatin	g to the real
402.					nformation has been prepared by		
403.					poses of this paragraph, "qualified		
404.					any person whom Seller or prospe		
405					industry standards of prostice for		

believes has the expertise necessary to meet the industry standards of practice for the type of inspection

information included in a written report under paragraph (1) if a copy of the report is provided to Seller.

or investigation that has been conducted by the third party in order to prepare the written report.

(2) Seller shall disclose to the prospective buyer material facts known by Seller that contradict any



405.

406.

407.

408.

409. Page 10

410.		THE INFORMAT	ION DISCLOSED IS GIVEN	TO THE BEST OF SELLER'S KNO	WLEDGE.
411.	Pro	operty located at 5652	Colfax Ave S	Minneapolis	MN 55419
412.	R.	ADDITIONAL COMME	NTS:		
413.					
414.					
415.					
416.					
417.					
418.					
419.					
420.	S.	SELLER'S STATEMEN	T:		
421.		(To be signed at time of	listing.)		
422.				true and accurate and authorizes any	
423. 424.				de a copy of this Disclosure Statemer the Property. A seller may provide th	
425.				prospective buyer. The Disclosure St	
426.				spective buyer is considered to have	
427.				rovided to the real estate licensee re	
428.		CONTRACTOR		provide a copy to the prospective b	10 4 Control
429. 430.				writing of any facts that differ fro that could adversely and significa	
431.				I use of the Property that occur up	
432.		To disclose new or char	iged facts, please use the Ar	mendment to Disclosure Statement	form.
		n	01-1-		
433.		Mi Kam	8/17/200	2	
		(Seller)	(Date)	(Seller)	(Date)
434.	T.	BUYER'S ACKNOWLE	DGEMENT:		
435.		(To be signed at time of	purchase agreement.)		
436.		I/We, the Buyer(s) of the	Property, acknowledge rece	eipt of this Seller's Property Disclosu	re Statement and agree
437.				ade other than those made above. Th	
438. 439.				ller or licensee(s) representing or as ns or warranties the party(ies) may w	
440.				F1. 15 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	isii to obtaiii.
440.		The information disclose	ed is given to the best of Sel	ier's knowledge.	
441.				-	
		(Buyer)	(Date)	(Buyer)	(Date)
442.		LISTING BROK	KER AND LICENSEES MAK	CE NO REPRESENTATIONS HERE	AND ARE
443.				DITIONS EXISTING ON THE PROPI	

MN:DS:SPDS-10 (8/22)



Radon in Real Estate Transactions



All Minnesota homes can have dangerous levels of radon gas. Radon is a colorless, odorless and tasteless radioactive gas that can seep into homes from the soil. When inhaled, its radioactive particles can damage the lungs. Long-term exposure to radon can lead to lung cancer. About 21,000 lung cancer deaths each year in the United States are caused by radon.

The only way to know how much radon gas has entered the home is to conduct a radon test. MDH estimates 2 in 5 homes exceed the 4.0 pCi/L (picocuries per liter) action level. Whether a home is old or new, any home can have high levels of radon.

The purpose of this publication is to educate and inform potential home buyers of the risks of radon exposure, and how to test for and reduce radon as part of real estate transactions.

Disclosure Requirements

Effective January 1, 2014, the Minnesota Radon Awareness Act requires specific disclosure and education be provided to potential home buyers during residential real estate transactions in Minnesota.

Before signing a purchase agreement to sell or transfer residential real property, the seller shall provide this publication and shall disclose in writing to the buyer:

- whether a radon test or tests have occurred on the property
- the most current records and reports pertaining to radon concentrations within the dwelling
- a description of any radon levels, mitigation, or remediation
- information on the radon mitigation system, if a system was installed
- 5. a radon warning statement

Radon Facts

How dangerous is radon? Radon is the number one cause of lung cancer in non-smokers, and the second leading cause overall. Your risk for lung cancer increases with higher levels of radon, prolonged exposure, and whether or not you are a current smoker or former smoker.

Where is your greatest exposure to radon? For most Minnesotans, your greatest exposure is at home where radon can concentrate indoors.

What is the recommended action based on my results? If the average radon in the home is at or above 4.0 pCi/L, the home's radon level should be reduced. Also, consider mitigating if radon levels are between 2.0 pCi/L and 3.9 pCi/L. Any amount of radon, even below the recommended action level, carries some risk.

Radon Warning Statement

"The Minnesota Department of Health strongly recommends that ALL homebuyers have an indoor radontest performed prior to purchase or taking occupancy, and recommends having the radon levels mitigated if elevated radon concentrations are found. Elevated radon concentrations can easily be reduced by a qualified, certified, or licensed, if applicable, radon mitigator.

Every buyer of any interest in residential real property is notified that the property may present exposure to dangerous levels of indoor radon gas that may place the occupants at risk of developing radon-induced lung cancer. Radon, a Class A human carcinogen, is the leading cause of lung cancer in nonsmokers and the second leading cause overall. The seller of any interest in residential real property is required to provide the buyer with any information on radon test results of the dwelling"







Radon Testing

Any test lasting less than three months requires closed-house conditions. This means keep all windows and doors closed, except for normal entry and exit.

Before testing: Begin closed-house conditions at least 12 hours before the start of the radon test.

During testing: Maintain closed-house conditions during the entire duration of the short-term test. Operate home heating or cooling systems normally during the test.

Where should the test be conducted? Any radon test conducted for a real estate transaction needs to be placed in the lowest livable area of the home suitable for occupancy. This is typically in the basement, whether finished or unfinished.

Place the test kit:

- 20 inches to 6 feet above the floor
- 9 3 feet from exterior doors and windows
- 1 foot from exterior walls

- 4 inches away from other objects
- in a location where it won't be disturbed
- not in enclosed areas or areas of high heat/humidity

How are radon tests conducted in real estate transactions?

There are special protocols for radon testing in real estate transactions. Here are the two most common.

Continuous Radon Monitor (CRM)

This test is completed by a certified radon measurement professional with a calibrated CRM for a minimum of 48 hours. The data is analyzed to ensure a valid test. A report is generated by the measurement professional.

Simultaneous Short-Term Testing

Two short-term test kits are used at the same time, placed 4 inches apart, for a minimum of 48 hours. Test kits are sent to the lab for analysis. The lab generates a report. The two test results are averaged to get the radon level.

All radon tests should be conducted by a licensed professional. This ensures the test was conducted properly, in the correct location(s), which includes testing the lowest liveable level in each unique foundation type and undre appropriate building conditions. A list of these licensed radon measurement professionals can be found at MDH's Radon web site.

Radon Mitigation

When elevated levels of radon are found, they can be easily reduced by a licensed professional. A list of these licensed radon mitigation professionals can be found on MDH's Radon website.

Radon mitigation is the process or system used to reduce radon concentrations in the breathing zones of occupied buildings. The goal of a radon mitigation system is to reduce the indoor radon levels to below the action level. This is done by drawing soil gas from under the house and venting it above the roof. A quality mitigation system is often able to reduce the annual average radon level to below 2.0 pCi/L. The cost of a radon mitigation system averages \$1,200 to \$2,500.

After a radon mitigation system is installed perform an independent short-term test to ensure the reduction system is effective. Operate the radon system during the entire test. This short-term test will confirm low levels in the home. Be sure to retest the house every two years to confirm continued radon reduction.

Radon Information on the Web:

www.health.state.mn.us/radon

Last Updated 3/2021

MDH Indoor Air Unit

PO Box 64975 St Paul, MN 55164-0975 651-201-4601 800-798-9050 health.indoorair@state.mn.us





Lakes | Sotheby's

ADDENDUM TO PURCHASE AGREEMENT: DISCLOSURE OF INFORMATION ON LEAD-BASED PAINT AND LEAD-BASED PAINT HAZARDS

This form approved by the Minnesota Association of REALTORS®, which disclaims any liability arising out of use or misuse of this form. © 2020 Minnesota Association of REALTORS®, Edina, MN

	1. Date <u>8/17/2022</u> 2. Page 1
3.	Addendum to Purchase Agreement between parties, dated
4.	(Date of this Purchase Agreement), pertaining to the purchase and sale of the Property a
5.	5652 Colfax Ave S Minneapolis MN 55419
6.	Lead Warning Statement
7.	Every buyer of any interest in residential real property on which a residential dwelling was built prior to 1978 is notified
8. 9.	that such property may present exposure to lead from lead-based paint that may place young children at risk o developing lead poisoning. Lead poisoning in young children may produce permanent neurological damage, including
10.	learning disabilities, reduced intelligence quotient, behavioral problems, and impaired memory. Lead poisoning also
11. 12.	poses a particular risk to pregnant women. The seller of any interest in residential real property is required to provide
13.	the buyer with any information on lead-based paint hazards from risk assessments or inspections in the seller's possession and notify the buyer of any known lead-based paint hazards. A risk assessment or inspection for possible
14.	lead-based paint hazards is recommended prior to purchase.
15.	Seller's Disclosure (Check one.)
16.	Seller has no knowledge of, or records or reports relating to, lead-based paint and/or lead-based paint hazards
17.	in the housing.
18. 19.	Seller has knowledge of lead-based paint and/or lead-based paint hazards in the housing and has provided Buyer with all available details, records, and reports, if any, pertaining to lead-based paint and/or lead-based paint
20.	hazards in the housing. (Please explain and list documents below.):
21.	1760) 56 (1766) 26 000000000000000000000000000000000
22.	
23.	
24.	Buyer's Acknowledgment
25.	Buyer has received copies of all information listed above, if any.
26.	Buyer has received the pamphlet, Protect Your Family from Lead in Your Home.
27.	Buyer has: (Check one.)
28.	☐ Waived the opportunity to conduct a risk assessment or inspection for the presence of lead-based paint and/or
29.	lead-based paint hazards; or
30. 31.	Received a 10-day opportunity (or mutually agreed-upon period) to conduct a risk assessment or inspection for the presence of lead-based paint and/or lead-based paint hazards.
32. 33.	If checked, this contract is contingent upon a risk assessment or an inspection of the property for the presence of lead-based paint and/or lead-based paint hazards to be conducted at Buyer's expense. The assessment or inspection
34.	shall be completed within TEN (10) Calendar Days after Final Acceptance of the Purchase
35.	Agreement.



ADDENDUM TO PURCHASE AGREEMENT: DISCLOSURE OF INFORMATION ON LEAD-BASED PAINT AND LEAD-BASED PAINT HAZARDS

36. Page 2

38.	This contingency shall be deemed removed, and							
39. 40.	This contingency shall be deemed removed, and the Purchase Agreement shall be in full force and effect unless Buyer or real estate licensee representing or assisting Buyer delivers to Seller or real estate licensee representing or assisting Seller, within three (3) Calendar Days after the assessment or inspection is timely							
41.								
42.								
43. 44.								
45.	And a state of the							
46.								
47.								
48.								
49.								
50.	Buyer or real estate licensee representing or assisting Buyer notifies Seller or real estate licensee representing or							
51.	assisting Seller of the waiver or removal, in writing, within the time specified.							
55. 56.	Certification of Accuracy	bases and and for the three bases of the size						
57.								
57.	information provided by the signatory is true and accura	ate.						
58.	Gir Dam 8/17/2022							
	(Seller) (Date)	(Buyer)	(Date)					
59.								
	(Seller) (Date)	(Buyer)	(Date)					
_	8/17/22							
60.	22							

TLX:SALE-2 (8/20)



NOTICE - Read Entire Report Carefully. This is not a rental license inspection or a buyer's inspection!

Address: 5652 COLFAX AVE S Minneapolis, MN



Current Owner Name: erin Rahman Contact: erin Rahman

Business/Relationship:

Owner Address: 5652 COLFAX AVE S

Minneapolis, MN 55419

Phone Number: 000-000-0000

******* SEE ATTACHED PAGES FOR IMPORTANT CONSUMER INFORMATION *******

Observed Number of Units: 1 City Reference as: 1

Building Type: Single Family Home **Zoning:** R1

To verify this structure complies with the current Zoning ordinance, please contact Zoning Administration via 311.

Housing Orders: No

Condemnation Status: NA Reason: NA

- 1. This report offers a limited overview of the building components and fixtures and is not technically extensive. Prospective buyers may want to seek additional opinions from various experts in the inspections field prior to purchase. This report is not a warranty or guarantee, expressed or implied, by the City of Minneapolis or by the evaluator or of any building component or fixture. Further, the buyer may want to seek additional information regarding any open permits. For 1st time condominium units, this report includes only those items located within the residential units. The Professional Opinion covers those items in the common areas of the building.
- 2. The buyer must repair all items marked Repair/Replace, unless the seller agrees to do the repairs. The seller is not required to complete the RR's if the property does not sell. All required R.R.'s items are enforceable by Minneapolis Ordinance Chapter 248 and/or 250. <u>All other items</u> will not be used by the Inspections Division as a basis for enforcing Minneapolis ordinances.
- 3. The ordinance requires that no person shall exhibit or show a dwelling for sale without first having obtained an official Evaluation Report and places the responsibility on the seller or agent to make sure that this report (and in the case of 1st time condo conversions, the Professional Opinion,) is publicly displayed on the premises at all times when the house is shown to prospective buyers. The seller or agent must give a copy of this report (and Professional Opinion for 1st time condo conversions) to the buyer prior to the signing of a Purchase Agreement, or as otherwise required in Minneapolis Ordinance Chapter 248 and/or 250.
- 4. This report covers only those items listed on the form. The evaluator is not required to ignite the heating plant, use a ladder to observe the condition of the roofing, evaluate inaccessible or concealed areas or disassemble items. This report does not address formaldehyde, lead paint, any airborne gasses (including radon), asbestos, wood stoves, fireplaces or air conditioners. Gas inserts in fireplaces WILL be evaluated.
- 5. This report is not an FHA, VA or Section 8 inspection. This report is not a code compliance inspection. It is not an appraisal. This report may be based upon different standards than the lender, FHA or VA. This is not a rental inspection. If planning to rent, additional requirements may apply and a license will be required.
- 6. The seller is required to provide the disclosure information in the box above. If this is not filled out, buyers are advised to request the seller to do so.
- 7. This report is valid for two years from the date of issue or one sale and <u>only for the owner</u> named on the report. It is required for all single-family homes, duplexes, townhouses or 1st time condominium conversions offered for sale.
- 8. **Any questions** regarding this report should be directed to the evaluator whose name and phone number appear below. **Any complaints** regarding this report should be directed to Truth in Housing at (612) 673-5840, Construction Code Services, 250 South 4th Street #300, Minneapolis, MN 55415.

I hereby certify that this report is made in compliance with the Minneapolis Code of Ordinances, Chapter 248, and that I utilized care and diligence reasonable and ordinary for one meeting the Certification Standards. The report covers only those problems listed and reasonably visible at the time of my evaluation and does not warrant future useful life of any house component or fixture. I have included all required information pages with this report.

Evaluator Name: Don Doty **Phone:** 952-544-8141 **Evaluation Date:** 8/10/2022

Signature: Don Doty Evaluation #: 20224698

Address: 5652 COLFAX AVE S Minneapolis, MN



EVALUATION CODES:

M:=Meets Minimum RequirementsC:=CommentsNA:=Not Applicable/Does Not ApplyB:=Below Minimum RequirementsSC:=Suggested CorrectionRRE:=Repair/Replace, Evaluator Verification RequiredRRP:=Repair/Replace, Permit/City Inspector RequiredLIC:=Safety Check, Licensed Contractor Required

Each item may have more than one code. Items marked "RRE" or "RRP" indicate that the item must be repaired or replaced within 90 days of closing. Items marked "LIC" require a licensed contractor to evaluate the safety of the item and may or may not require a repair. Buyer must sign acknowledgment of responsibility agreement unless a Certificate of Approval (COA) has been issued to seller. If the house doesn't sell, the seller does not have to do the repairs. See attached handout on the "MOST COMMON REPAIRS".

Basement

Finished off/areas concealed, unable to fully evaluate - walls/ floor /ceilings/covered

- 1. Basement Stairs/Railings
 - B, Stairway headroom is less than 6'8".
- 2. Basement Floors
 - M, Meets Minimum Requirements
- 3. Foundation Walls
 - M, Meets Minimum Requirements
- 4. Evidence of Dampness or Staining
 - M, Meets Minimum Requirements
- 5. First Floor, Floor System
 - M, Meets Minimum Requirements
- 6. Columns & Beams
 - M, Meets Minimum Requirements
- 7. Basement Sleeping Rooms
 - M, Meets Minimum Requirements
- 8. Basement Plumbing Fixtures
 - C, Other Comment: toilet,sink,shower
- 9. Sump Pumps
 - NA, Not Applicable/Does Not Apply
- 10. Smoke Detectors / CO Detectors
 - M, Meets Minimum Requirements
- 11. Basement Electrical Outlets/Fixtures
 - M, Meets Minimum Requirements

Electric

Amps: 100

Volts: 110/220

- 12. Electrical service installation
 - M, Meets Minimum Requirements
- 13. Separate 20-amp Kitchen Circuit indexed at Service Panel
 - M, Meets Minimum Requirements
- 14. Separate 20-amp Laundry Circuit indexed at Service Panel

M, Meets Minimum Requirements

Evaluator Name: Don Doty **Evaluation Date:** 8/10/2022 Page 2 of 13

Address: 5652 COLFAX AVE S Minneapolis, MN



EVALUATION CODES:

M :=Meets Minimum Requirements C :=Comments RRE :=Repair/Replace, Evaluator Verification Required RRP :=Repair/Replace, Permit/City Inspector Required LIC :=Safety Check, Licensed Contractor Required

Each item may have more than one code. Items marked "RRE" or "RRP" indicate that the item must be repaired or replaced within 90 days of closing. Items marked "LIC" require a licensed contractor to evaluate the safety of the item and may or may not require a repair. Buyer must sign acknowledgment of responsibility agreement unless a Certificate of Approval (COA) has been issued to seller. If the house doesn't sell, the seller does not have to do the repairs. See attached handout on the "MOST COMMON REPAIRS".

Plumbing

15. Floor Drains

M, Meets Minimum Requirements

Drain, Waste & Vent Piping

M, Meets Minimum Requirements

17. Water Supply Piping

M, Meets Minimum Requirements

18. Gas Piping

M, Meets Minimum Requirements

19. Copper Water Line Visible on the Street Side of Water Meter

C, Water line is not visible. - floor covers most of pipe

Water heater

20. Water Heater & Installation

M, Meets Minimum Requirements

21. Water Heater Venting

M, Meets Minimum Requirements

Heating

Heating System Type: forced air furnace

Heating System Venting Type: natural draft

22. Heating Plant Viewed in Operation

M, Meets Minimum Requirements

23. Heating Plant & Installation

M, Meets Minimum Requirements

24. Heating Plant Combustion Venting

M, Meets Minimum Requirements

25. Incinerator / Abandoned Oil Tanks / Misc Gas Fixtures

NA, Not Applicable/Does Not Apply

Evaluator Name: Don Doty **Evaluation Date:** 8/10/2022 Page 3 of 13

Address: 5652 COLFAX AVE S Minneapolis, MN



EVALUATION CODES:

M :=Meets Minimum Requirements C :=Comments RRE :=Repair/Replace, Evaluator Verification Required RRP :=Repair/Replace, Permit/City Inspector Required LIC :=Safety Check, Licensed Contractor Required

Each item may have more than one code. Items marked "RRE" or "RRP" indicate that the item must be repaired or replaced within 90 days of closing. Items marked "LIC" require a licensed contractor to evaluate the safety of the item and may or may not require a repair. Buyer must sign acknowledgment of responsibility agreement unless a Certificate of Approval (COA) has been issued to seller. If the house doesn't sell, the seller does not have to do the repairs. See attached handout on the "MOST COMMON REPAIRS".

Laundry

26. Gas Piping

M, Meets Minimum Requirements

27. Dryer Venting

M, Meets Minimum Requirements

28. Plumbing Fixtures

M, Meets Minimum Requirements

Kitchen

29. Walls and Ceiling Components

M, Meets Minimum Requirements

30. Evidence of Dampness or Staining

M, Meets Minimum Requirements

31. Floor Condition

M, Meets Minimum Requirements

32. Window Size & Openable Area

M, Meets Minimum Requirements

33. Window & Door Condition/Mechanical Venting

M, Meets Minimum Requirements

34. Electrical Outlets/Fixtures

M, Meets Minimum Requirements

35. Plumbing Fixtures

M, Meets Minimum Requirements

36. Water Flow

M, Meets Minimum Requirements

37. Gas Piping

M, Meets Minimum Requirements

Evaluator Name: Don Doty **Evaluation Date:** 8/10/2022 Page 4 of 13

Address: 5652 COLFAX AVE S Minneapolis, MN



EVALUATION CODES:

M :=Meets Minimum Requirements C :=Comments RRE :=Repair/Replace, Evaluator Verification Required

NA :=Not Applicable/Does Not Apply B :=Below RRP :=Repair/Replace, Permit/City Inspector Required

B :=Below Minimum Requirements SC :=Suggested Correction r Required LIC :=Safety Check, Licensed Contractor Required

Each item may have more than one code. Items marked "RRE" or "RRP" indicate that the item must be repaired or replaced within 90 days of closing. Items marked "LIC" require a licensed contractor to evaluate the safety of the item and may or may not require a repair. Buyer must sign acknowledgment of responsibility agreement unless a Certificate of Approval (COA) has been issued to seller. If the house doesn't sell, the seller does not have to do the repairs. See attached handout on the "MOST COMMON REPAIRS".

Dining Room/Living Room

38. Walls and Ceiling Components

M, Meets Minimum Requirements

39. Evidence of Dampness or Staining

M, Meets Minimum Requirements

40. Floor Area & Ceiling Height

M, Meets Minimum Requirements

41. Floor Condition

M, Meets Minimum Requirements

42. Window Size & Openable Area

M, Meets Minimum Requirements

43. Window & Door Condition

M, Meets Minimum Requirements

44. Electrical Outlets/Fixtures

M, Meets Minimum Requirements

Bathroom (basement)

45. Walls & Ceiling Components

M, Meets Minimum Requirements

46. Evidence of Dampness or Staining

M, Meets Minimum Requirements

47. Floor Condition

M, Meets Minimum Requirements

48. Window Size & Openable Area/Mechanical Vent

M, Meets Minimum Requirements

49. Window & Door Condition

M, Meets Minimum Requirements

50. Electrical Outlets & Fixtures

M, Meets Minimum Requirements

51. Plumbing Fixtures

M, Meets Minimum Requirements

52. Water Flow

M, Meets Minimum Requirements

Evaluator Name: Evaluation Date: Don Doty 8/10/2022 Page 5 of 13

Address: 5652 COLFAX AVE S Minneapolis, MN



EVALUATION CODES:

M :=Meets Minimum Requirements C :=Comments RRE :=Repair/Replace, Evaluator Verification Required RRP :=Repair/Replace, Permit/City Inspector Required LIC :=Safety Check, Licensed Contractor Required

Each item may have more than one code. Items marked "RRE" or "RRP" indicate that the item must be repaired or replaced within 90 days of closing. Items marked "LIC" require a licensed contractor to evaluate the safety of the item and may or may not require a repair. Buyer must sign acknowledgment of responsibility agreement unless a Certificate of Approval (COA) has been issued to seller. If the house doesn't sell, the seller does not have to do the repairs. See attached handout on the "MOST COMMON REPAIRS".

Bathroom (1st floor)

45. Walls & Ceiling Components

M, Meets Minimum Requirements

46. Evidence of Dampness or Staining

M, Meets Minimum Requirements

47. Floor Condition

M, Meets Minimum Requirements

48. Window Size & Openable Area/Mechanical Vent

M, Meets Minimum Requirements

49. Window & Door Condition

M, Meets Minimum Requirements

50. Electrical Outlets & Fixtures

M, Meets Minimum Requirements

51. Plumbing Fixtures

M, Meets Minimum Requirements

52. Water Flow

M, Meets Minimum Requirements

Bathroom (2nd floor)

45. Walls & Ceiling Components

M, Meets Minimum Requirements

46. Evidence of Dampness or Staining

M, Meets Minimum Requirements

47. Floor Condition

M, Meets Minimum Requirements

48. Window Size & Openable Area/Mechanical Vent

M, Meets Minimum Requirements

49. Window & Door Condition

M, Meets Minimum Requirements

50. Electrical Outlets & Fixtures

M, Meets Minimum Requirements

51. Plumbing Fixtures

M, Meets Minimum Requirements

52. Water Flow

M, Meets Minimum Requirements

Evaluator Name: Don Doty **Evaluation Date:** 8/10/2022 Page 6 of 13

Address: 5652 COLFAX AVE S Minneapolis, MN



EVALUATION CODES:

M :=Meets Minimum Requirements C :=Comments RRE :=Repair/Replace, Evaluator Verification Required

NA :=Not Applicable/Does Not Apply B :=Below RRP :=Repair/Replace, Permit/City Inspector Required

B :=Below Minimum Requirements SC :=Suggested Correction r Required LIC :=Safety Check, Licensed Contractor Required

Each item may have more than one code. Items marked "RRE" or "RRP" indicate that the item must be repaired or replaced within 90 days of closing. Items marked "LIC" require a licensed contractor to evaluate the safety of the item and may or may not require a repair. Buyer must sign acknowledgment of responsibility agreement unless a Certificate of Approval (COA) has been issued to seller. If the house doesn't sell, the seller does not have to do the repairs. See attached handout on the "MOST COMMON REPAIRS".

Hallways/Stairwells

53. Walls and Ceiling Components

M, Meets Minimum Requirements

54. Evidence of Dampness or Staining

M, Meets Minimum Requirements

55. Floor Condition

M, Meets Minimum Requirements

56. Window & Door Condition

M, Meets Minimum Requirements

57. Electrical Outlets/Fixtures

M, Meets Minimum Requirements

58. Stairs and Railings

M, Meets Minimum Requirements

59. Smoke Detectors /CO Detectors

M, Meets Minimum Requirements

Bedroom (basement)

60. Walls and Ceiling Components

M, Meets Minimum Requirements

61. Evidence of Dampness or Staining

M, Meets Minimum Requirements

62. Floor Area & Ceiling Height

M, Meets Minimum Requirements

63. Floor Condition

M, Meets Minimum Requirements

64. Window Size & Openable Area

M, Meets Minimum Requirements

65. Window & Door Condition

M, Meets Minimum Requirements

66. Electrical Outlets/Fixtures

M, Meets Minimum Requirements

Evaluator Name: Evaluation Date: Don Doty 8/10/2022 Page 7 of 13

Address: 5652 COLFAX AVE S Minneapolis, MN



EVALUATION CODES:

M :=Meets Minimum Requirements C :=Comments RRE :=Repair/Replace, Evaluator Verification Required RPP :=Repair/Replace, Permit/City Inspector Required LIC :=Safety Check, Licensed Contractor Required

Each item may have more than one code. Items marked "RRE" or "RRP" indicate that the item must be repaired or replaced within 90 days of closing. Items marked "LIC" require a licensed contractor to evaluate the safety of the item and may or may not require a repair. Buyer must sign acknowledgment of responsibility agreement unless a Certificate of Approval (COA) has been issued to seller. If the house doesn't sell, the seller does not have to do the repairs. See attached handout on the "MOST COMMON REPAIRS".

Bedroom (1st floor east)

60. Walls and Ceiling Components

M, Meets Minimum Requirements

61. Evidence of Dampness or Staining

M, Meets Minimum Requirements

62. Floor Area & Ceiling Height

M, Meets Minimum Requirements

63. Floor Condition

M, Meets Minimum Requirements

64. Window Size & Openable Area

M, Meets Minimum Requirements

65. Window & Door Condition

M, Meets Minimum Requirements

66. Electrical Outlets/Fixtures

M, Meets Minimum Requirements

Bedroom (1st floor west)

60. Walls and Ceiling Components

M, Meets Minimum Requirements

61. Evidence of Dampness or Staining

M, Meets Minimum Requirements

62. Floor Area & Ceiling Height

M, Meets Minimum Requirements

63. Floor Condition

M, Meets Minimum Requirements

64. Window Size & Openable Area

M, Meets Minimum Requirements

65. Window & Door Condition

M, Meets Minimum Requirements

66. Electrical Outlets/Fixtures

M, Meets Minimum Requirements

Evaluator Name: Don Doty **Evaluation Date:** 8/10/2022 Page 8 of 13

Address: 5652 COLFAX AVE S Minneapolis, MN



EVALUATION CODES:

M :=Meets Minimum Requirements C :=Comments RRE :=Repair/Replace, Evaluator Verification Required RRP :=Repair/Replace, Permit/City Inspector Required LIC :=Safety Check, Licensed Contractor Required

Each item may have more than one code. Items marked "RRE" or "RRP" indicate that the item must be repaired or replaced within 90 days of closing. Items marked "LIC" require a licensed contractor to evaluate the safety of the item and may or may not require a repair. Buyer must sign acknowledgment of responsibility agreement unless a Certificate of Approval (COA) has been issued to seller. If the house doesn't sell, the seller does not have to do the repairs. See attached handout on the "MOST COMMON REPAIRS".

Bedroom (2nd floor)

60. Walls and Ceiling Components

M, Meets Minimum Requirements

Evidence of Dampness or Staining

M, Meets Minimum Requirements

62. Floor Area & Ceiling Height

M, Meets Minimum Requirements

63. Floor Condition

M, Meets Minimum Requirements

64. Window Size & Openable Area

M, Meets Minimum Requirements

65. Window & Door Condition

M, Meets Minimum Requirements

66. Electrical Outlets/Fixtures

M, Meets Minimum Requirements

Porch/Sunroom/Other

Not Applicable

Attic Space

Attic Type: peak

Attic Is Accessible?: no

Estimated Attic Insulated Sq Ft: 880

72. Roof Boards & Rafters / Ventilation

NA, Not Applicable/Does Not Apply

73. Evidence of Dampness or Staining

NA, Not Applicable/Does Not Apply

74. Electrical Outlets & Fixtures

NA, Not Applicable/Does Not Apply

75. Mechanical Venting

NA, Not Applicable/Does Not Apply

Evaluator Name: Don Doty **Evaluation Date:** 8/10/2022 Page 9 of 13

Address: 5652 COLFAX AVE S Minneapolis, MN



EVALUATION CODES:

M :=Meets Minimum Requirements C :=Comments RRE :=Repair/Replace, Evaluator Verification Required RRP :=Repair/Replace, Permit/City Inspector Required LIC :=Safety Check, Licensed Contractor Required

Each item may have more than one code. Items marked "RRE" or "RRP" indicate that the item must be repaired or replaced within 90 days of closing. Items marked "LIC" require a licensed contractor to evaluate the safety of the item and may or may not require a repair. Buyer must sign acknowledgment of responsibility agreement unless a Certificate of Approval (COA) has been issued to seller. If the house doesn't sell, the seller does not have to do the repairs. See attached handout on the "MOST COMMON REPAIRS".

Exterior

Estimated number of single pane windows without storms: 0

Roof viewed from the ground

76. Foundation

M, Meets Minimum Requirements

77. Basement Windows

M, Meets Minimum Requirements

78. Drainage (Grade) / Rainleaders

C, Other Comment: - some flat areas around house

79. Exterior Walls

M, Meets Minimum Requirements

80. Doors (frames/storms/screens/deadbolt locks)

B, Missing storm door.

81. Windows (frames/storms/screens)

M, Meets Minimum Requirements

82. Stoops

M, Meets Minimum Requirements

83. Cornice & Trim

M, Meets Minimum Requirements

84. Roof Covering & Flashing

C. Portions of roof are not visible. - low pitch roof not able to view

85. Chimney

M, Meets Minimum Requirements

86. Electrical Outlets/Fixtures

M, Meets Minimum Requirements

87. Exterior Plumbing-Backflow Prevention

M, Meets Minimum Requirements

88. Two-Family Dwelling Egress

NA, Not Applicable/Does Not Apply

Open/Unheated Porch

Not Applicable

Evaluator Name: Don Doty **Evaluation Date:** 8/10/2022 Page 10 of 13

Address: 5652 COLFAX AVE S Minneapolis, MN



EVALUATION CODES:

M :=Meets Minimum Requirements C :=Comments RRE :=Repair/Replace, Evaluator Verification Required RRP :=Repair/Replace, Permit/City Inspector Required LIC :=Safety Check, Licensed Contractor Required

Each item may have more than one code. Items marked "RRE" or "RRP" indicate that the item must be repaired or replaced within 90 days of closing. Items marked "LIC" require a licensed contractor to evaluate the safety of the item and may or may not require a repair. Buyer must sign acknowledgment of responsibility agreement unless a Certificate of Approval (COA) has been issued to seller. If the house doesn't sell, the seller does not have to do the repairs. See attached handout on the "MOST COMMON REPAIRS".

Garage

- 94. Roof Structure & Covering
 - M, Meets Minimum Requirements
- 95. Wall Structure & Covering
 - B, Weathered/damaged siding trim.
 - B, Siding lacks clearance to grade.
- 96. Garage Doors
 - B, Weathered/deteriorated overhead door(s).
- 97. Automatic Garage Door Opener
 - M, Meets Minimum Requirements
- 98. Electrical Outlets/Fixtures
 - M, Meets Minimum Requirements

Miscellaneous

- 99. Clutter/Sanitation/Vermin
 - M, Meets Minimum Requirements
- 100. Other
 - M, Meets Minimum Requirements

Wall Insulation

Wall Insulation Depth: 5 inches Wall Insulation Type: Fiberglass

Evaluator Name: Don Doty **Evaluation Date:** 8/10/2022 Page 11 of 13

Address: 5652 COLFAX AVE S Minneapolis, MN



Truth in Housing Repair Notification

City of Minneapolis - Truth in Sale of Housing 250 South 4th Street, Room 300 Minneapolis, MN 55415

Issued To: 8/10/2022

erin Rahman 5652 COLFAX AVE S Minneapolis, MN 55419

Owner does not have to complete repairs if the house is not sold.

Pursuant to Minneapolis Code of Ordinances, Sections 248.20 and 248.225, the owner may make the repairs. If the owner makes the repairs, a Certificate of Approval (needed for closing) will be issued after the repairs have been inspected and approved. The owner does not have to complete the repairs if the house does not sell. If the owner does not make the repairs, the buyer must sign an acknowledgement of responsibility form (provided by the City) and return it to the City. The buyer has 90 days from closing to complete the repairs. Your prompt cooperation in attending to the repair items is appreciated however, failure to comply by these deadlines may result in legal action.

REQUIRED REPAIRS

NONE

SAFETY CHECKS

The systems listed below must be checked by a licensed contractor. The contractor must be licensed by the City of Minneapolis and/or the State of Minnesota in that specific trade to check the work. Return safety check forms to the address above or fax to (612) 673-2437. If "Evaluator Return" is indicated below, the evaluator may return to view the system that was not in operation at the time of the initial evaluation. The evaluator may find additional work is needed on the system.

If the system was repaired or replaced, only a licensed contractor (not the evaluator) can do the safety check. Permits may be needed.

NONE

PERMIT REQUIRED REPAIR

The permit must be pulled before scheduling. Call the inspector listed on the permit to set an appointment. You need to have the permit number to set the appointment. There will be a charge for the permit, which covers the inspection.

NONE

Reinspection Process

When all the items are completed they must be inspected and approved.

For items that need a permit:

If your notification indicates PERMIT NEEDED, the permit(s) must be pulled and work completed BEFORE the re-inspection takes place. If you are a homeowner occupant of a single family house, you may obtain a permit, if you are not, you must hire a licensed contractor. Bring this notification with you when you apply for permits.

For items that do not need a permit:

Call the evaluator who did the initial TISH report to re-inspect all the non-permit items. The evaluator's name and phone number are on the bottom of page 1 of the report. There will be a charge for this inspection.

Evaluator Name: Don Doty **Evaluation Date:** 8/10/2022 Page 12 of 13

Address: 5652 COLFAX AVE S Minneapolis, MN



Appeal

This repair notice may be appealed. Section 248.150 of the Minneapolis Code of Ordinances provides that an appeal must be filed in writing within thirty (30) days of the date of this notice accompanied with a \$100 filing fee. If you wish to appeal this order, call (612) 673-5840 for an application.

Assistance

If you need financial assistance to complete these repairs, you may call the Center for Energy and Environment at 612-335-5884.

Evaluator Name: Don Doty **Evaluation Date:** 8/10/2022 Page 13 of 13



Energy Disclosure Report

Home Profile

Location:

5652 COLFAX AVE S Minneapolis, MN 55419

Year built: 1947 House sq. ft.: 2,744

Number of stories: 1.75 Visit Date: 8/10/22

How it Works

The energy score for your home is similar to MPG for a car, but it evaluates the energy performance of the home. The higher the home scores, the lower your energy bills will be.

Improve your score by completing the energy improvements below.


Homes with the highest scores typically sell for 2-6% more.**

When you are ready to begin, contact an Energy Advisor at 651-328-6225.

They can answer questions and connect you to helpful resources.

Financing and rebates are available from the City of Minneapolis and CenterPoint Energy to help you complete these energy improvements.

Energy Score



Home Energy Summary

Your home is less energy efficient than most homes in Minneapolis. You have multiple opportunities to increase your home's comfort and decrease energy bills by making cost-effective energy improvements. To learn more visit mncee.org/TISH or contact an Energy Advisor.

	Energy Improvements (by priority)	Improvement Points	Typical Cost	Utility Rebate	Yearly Bill Savings
Heating System	Upgrade your furnace	27	\$3,500- \$6,000	Up to \$500	\$150-\$300
Attic Insulation	Air seal and insulate your attic	9	\$2,650- \$3,250	Up to \$500	\$150-\$300
Wall Insulation	Energy Badge earned! Your home has efficient wall insulation.				
Storm Windows	All single-pane windows have storm windows.				





Next Step:Contact an Energy Advisor





Mike

Kat

651-328-6225 or energydisclosure@mncee.org mncee.org/TISH

An Energy Advisor can help:







Connect you to financing and utility rebates



Refer you to trusted contractors

The energy advisor service is provided by CEE with funding from CenterPoint Energy.

27 improvement points

Prioritized Energy Improvements

Current efficiency: 65-70%

Recommended efficiency: 96% or better

Heating System

Upgrade your furnace. Your furnace's basic natural draft system makes it possible for gases like carbon monoxide to spill back into your home, posing a potential risk to your indoor air quality and health. The best solution is to replace your furnace with a model that has an efficiency (AFUE) of at least 96% and an electronically commutated motor (ECM). This upgrade will modernize your heating system, properly remove combusted gases from your home, and maximize your energy savings.

Typical Cost:* \$3,500-\$6,000

Yearly Bill Savings:* \$150-\$300

Rebate Available: Up to \$500

Current attic insulation depth: No access

Recommended attic insulation depth: 16 inches

Attic Insulation

9 improvement points

Air seal and insulate your attic to improve the comfort of your home. I was not able to fully inspect your attic. However, research indicates that homes of a similar age and construction typically are not properly insulated or air-sealed. This can be especially true with half story homes like yours. Do this work to prevent ice dams, lower energy bills and increase your home's comfort and durability. Contact an Energy Advisor to learn more and get help with next steps.

Typical Cost:* \$2,650-\$3,250


Yearly Bill Savings:* \$150-\$300

Rebate Available: Up to \$500

^{*}The typical cost for each project is calculated by taking the average of thousands of homes of a similar age and construction. The estimated savings is the average reported savings for homes that received a utility rebate. Actual cost and savings may vary. Please contact an Energy Advisor if you have questions.

^{**} Multiple studies referenced by the U.S. Department of Energy show that homes that are labeled as energy efficient sell for 2-6% more.

This home has energy efficient wall insulation.







This home has energy efficient wall insulation.

The energy inspection of this home found efficient levels of wall insulation. The benefits include:

Better comfort — efficient wall insulation helps homes stay warmer in the winter and cooler in the summer.

Lower energy bills — efficient wall insulation saves up to \$400 a year on heating and cooling.

For more information visit **mncee.org/tish**.

Energy Badge Earned



Energy Badges are delivered by Center For Energy And Environment, a local energy nonprofit.

Curious about additional ways to save energy in your home? Contact an Energy Advisor today.

651-328-6225 or energydisclosure@mncee.org

